

1. INTRODUCTION

HP03 DEMO is a demonstration for HP03 application, it has 3 demo modes:


1. barometer mode:
2. Thermometer mode:
3. Altimeter mode:

2. OPERATION

2.1 Power Supply: this demo board use 3 X AA batteries, and insert them into battery cells on the back of board, please ensure the batteries are positive/negative polar correct.

2.2 After power on, the demo board enter barometer mode automatically.

2.3 botton can switch three kind of function display, the default is press value. The following illustration display convert by Press button :



HOPE MICROELECTRONICS CO.,LTD

4/F, Block B3, East Industrial Area,
Huaqiaocheng, Shenzhen, Guangdong,
China

Tel: 86-755-86096602

Fax: 86-755-86096587

Email: sales@hoperf.com

Website: <http://www.hoperf.com>

<http://www.hoperf.cn>

<http://hoperf.en.alibaba.com>

This document may contain preliminary information and is subject to change by Hope Microelectronics without notice. Hope Microelectronics assumes no responsibility or liability for any use of the information contained herein. Nothing in this document shall operate as an express or implied license or indemnity under the intellectual property rights of Hope Microelectronics or third parties. The products described in this document are not intended for use in implantation or other direct life support applications where malfunction may result in the direct physical harm or injury to persons. NO WARRANTIES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, ARE OFFERED IN THIS DOCUMENT.

©2006, HOPE MICROELECTRONICS CO.,LTD. All rights reserved.